



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06



Site Name: Ray Wichert Property CERCLIS ID#: OKD987095049

Alias Site Names: \_\_\_\_\_

Address: 10th Street and Industrial Boulevard

City/County or Parish/State/Zip Code: Clinton/Custer/Oklahoma/73601

Report Type, Date, and Author: Preliminary Assessment/July 29, 1992/Oklahoma State Department of Health (OSDH)

**RECOMMENDATION**

- ☒ 1. Site Evaluation Accomplished (SEA) ☐ 2. Further Investigation Needed Under Superfund
- ☐ PA ☐ HRS Priority: ☐ High  
☐ SI ☐ RA ☐ Low  
☐ ESI ☐ RI/FS  
☐ Other: \_\_\_\_\_  
To be performed by: \_\_\_\_\_
- ☐ 3. Action Deferred to:  
☐ RCRA ☐ NRC

**NOTIFY AUTHORITY:**

- ☐ Removal ☐ RCRA ☐ TSCA ☐ CAA ☐ SMCRA  
☐ Remedial ☐ State ☐ NPDES ☐ NRC ☐ Resource Trustee: \_\_\_\_\_  
☐ CERCLA Enforcement ☐ Federal Facility ☐ UIC ☐ SPCC ☐ Other: \_\_\_\_\_  
**SEND REPORT COPIES TO:** ☒ 6E-E ☒ 6W-SP ☐ ATSDR ☐ State Agency ☐ Other: \_\_\_\_\_

**DISCUSSION:** The Ray Wichert Property (the "site") is a 2 acre inactive dump site. At the time of construction, the site had been excavated approximately 15 feet lower than the eastern site boundary. The site had been utilized for the disposal of concrete, construction material and asphalt and may contain radium-contaminated sludge from the refurbishing of aircraft dials at the Sooner Dial Company. Samples have been obtained from the site during different sampling events; all analytical results indicate sufficient contamination to warrant removal. Rubble from the Sooner Dial Company and drums located at the site are the identified sources.

Groundwater in the site area is obtained from shallow groundwater (estimated at 8 persons); however, the nearest drinking water well to the site is located 2.5 miles northeast of the site. Perennial surface water is found at a distance greater than 2 miles from the site and no active intakes have been identified within the 15-mile instream segment. On-site soil contamination is suspected; however, no on-site workers, residences, schools or daycares are located within 200 feet of the suspected contamination. A release to the air pathway is not suspected due to the characteristics of the waste material and the physical conditions at the site (e.g., highly vegetated and excavated landscape).

Due to the lack of targets and a viable mechanism for transport of the hazardous materials on site, it is recommended that no further action under Superfund be taken at this time.

**APPROVALS:**

Report Reviewed by:	<u>Kim T. Hill</u>	Signature:	<u><i>Kim T. Hill</i></u>	Date:	<u>Jan/06/93</u>
Disposition Recommended by:	<u>Eddie A. Sierra</u>	Signature:	<u><i>Eddie A. Sierra</i></u>	Date:	<u>01/06/93</u>
(Section Chief)					
Disposition Approved by:	<u><i>For</i> Betty Williamson</u>	Signature:	<u><i>Vernice McFarland</i></u>	Date:	<u>1/7/93</u>
(Branch Chief)					

0

4

0

6